

# DCS Technical Team Repair/Installation Request



<b>1.</b>	<b>Location(s)</b>	<b>Control #</b>
	Pico Rivera Station DCS Room 6631 Passons Blvd. Pico Rivera, CA 90660	PRV-01
<b>2.</b>	<b>Statement of the Problem(s)</b>	
	<p>A. Kenwood TM641A 2 meter/220 radio. Non-functioning buttons don't allow programming memory channels. Functions only in VFO mode. The 2 meter antenna exhibits 1.7:1 SWR at 147.270.</p> <p>B. Kenwood TM-741 2 meter / 440 radio. 2 meter antenna SWR is 1.6:1 @ 145.300 &amp; 147.270 440 antenna SWR is Infinity:1</p> <p>C. Left Hand IC-726 HF &amp; 6 meter radio. Antenna SWR is Infinity:1 on all bands</p> <p>D. Right Hand IC-726 HF &amp; 6 meter radio. 6 meter antenna SWR is 1.5:1 @ 51.50 MHz HF antenna SWR is 3.5:1 @ 29.50 MHz HF antenna SWR is Infinity:1 on all other HF frequencies.</p>	
<b>3.</b>	<b>Recommended Solution(s)</b>	
	<p>A. Replace radio with an Alinco DR-235 MkIII for 220 and a Motorola CDM 1550 for 2m. Both are in CFMB stock. Attach to the same antennas that were on the TM-641A. Inspect and repair the 2 meter antenna.</p> <p>B. Inspect and repair both antennas</p> <p>C. Inspect and repair antenna system.</p> <p>D. Inspect and repair antenna system.</p>	
<b>4.</b>	<b>Concurrences</b>	<b>Date</b>
	<b>Technical Team Contact</b>	Keith Prebble, S12, <a href="mailto:kd6pyd@earthlink.net">kd6pyd@earthlink.net</a>
	<b>DCO</b>	Dave Olney Q-01, <a href="mailto:dave@otstudios.com">dave@otstudios.com</a>
	<b>Technical Ops Officer</b>	Deane Bouvier , S-50, <a href="mailto:n5dq@arrl.net">n5dq@arrl.net</a>
<b>5.</b>	<b>CFMB Approval</b>	