

DCS Technical Team Repair/Installation Request



1.	Location(s)	Control #
	Lancaster, Sheriff Station 501 West Lancaster Blvd. Lancaster, CA 93534	LAN-01
2.	Statement of the Problem(s)	
	A. Kenwood TM241 2m radio, Tag # 1293, Receive weak, Bad audio on transmit, Display issues	
3.	Recommended Solution(s)	
	A. Replace the radio with an Icom IC 2200H Test the antenna and repair or replace with a PD-220-2, 142-150 MHz, Cell wave Super Station Master as necessary. Both the radio and antenna are in CFMB stock.	
4.	Concurrences	Date
	Technical Team Contact	Steve Ioerger, F-01, machiamist@aol.com
	DCO	Tom Fischer, L-01, tomtnjranch@sbcglobal.net
	Technical Ops Officer	Deane Bouvier, S-50, n5dq@arri.net
5.	CFMB Approval	