DCS Technical Team Repair/Installation Request



1.	Location(s)		Control #
	Lomita Sheriff Station DC 26123 S. Narbonne Avenu		LMT-02
2.	Statement of the Problem(s)		
	meter shows no indicat room. Open squelch w	radio has developed a receiver problem. Sign tion, even when listening to the 50 watt Motor white noise level is abnormally low. Antenna c SD Inventory Tag AA006620	ola radio in the same
3.	Recommended Solution(s) A. Replace with ICOM 2200H with one from CFMB stock. Resolution S/N 0527705, LASD Inventory # AA006623 substituted for defective unit.		
4.	Concurrences		Date
4.	Concurrences Technical Team Contact	Deane Bouvier, S-50, <u>n5dq@arrl.net</u>	6/3/2015
4.	Technical Team Contact DCO	Dianna Feinberg, T-01, dfeinberg@att.net	6/3/2015 6/3/2015
4.	Technical Team Contact		6/3/2015
4.	Technical Team Contact DCO	Dianna Feinberg, T-01, dfeinberg@att.net	6/3/2015 6/3/2015