

Adaptor- 900 to 475

Use a 475V GM probe on a Geiger Counter that has only 900V HV.

Adjust number of Zeners and any HV lower than the original can be supplied.

