

# SERVICE NOTES

*turned to tomorrow*

# National

NATIONAL COMPANY, INC., 51 SHEPARD ST., NEWTON 45, MASS. • PHONE MA 7-7531 • CABLE "NATCO" BOSTON

Service Bulletin FSN-32

To: All Distributors, Service  
Agencies and Representatives

From: Robert J. Murray

November 18, 1955


SUBJECT: Replacement 4H4C Ballast Tubes Used in the HRO-60 and NC-300

It has been called to our attention that some difficulty is being experienced in the field obtaining replacement 4H4C ballast tubes as used in the NC-300 and the HRO-60.

We wish to advise that these current regulator tubes are carried by our Service Department and are set to you at \$1.80. Suggested retail price \$2.75.

In the event that a replacement 4H4C tube is not immediately available, your customer can use his receiver temporarily by merely plugging a 6V6 type tube in the 4H4C socket until the proper replacement is received.

RJM/s

  
Robert J. Murray, WLFEN  
Service Manager