

Mar 30, 2015 4:56 PM, "James Glancy" <[jbglancy@gmail.com](mailto:jbglancy@gmail.com)> wrote:  
Deane,

I put in two repair requests for Carson. If the 6 meter blanking problem is vertical antenna proximity, then an HF dipole (or end-fed) might be a perfect solution at that location. The HF rig is an FT897 with a manual (SGC?) tuner.

The other is a little Astron amperage shortage aka one power supply short.

What else do I need to fill out for the record?

Jim

