



Date	Revision/Addition/ Note	by
Sept 6, 2008	The Schematic I had for this supply was pretty poor. Redrew it from the schematic and by repairing a supply. May be mistakes in it but should be good enough for most maintenance/repairs.	GSC

Drawn By: Gerald Crenshaw WD4BIS	Date: Sept 6, 2008	From the bench of: Amateur Radio Station WD4BIS	Page 1
Engineer: Gerald Crenshaw WD4BIS	Date: Sept 6, 2008		of 1
Checked By: Janet Crenshaw WB9ZPH	Date: Sept 6, 2008		Title: Redraw of Austron RS 20A Power Supply. Austron Corp, Irvine Ca.