DCS Technical Team Repair/Installation Request



1.	Location(s)		Control #
	Lost Hills Sheriff Station A	Intenna Tower	LHS-01
	27050 Agoura Road, Agour	ra, CA 91301-5336	
2.	Statement of the Problem(s)		
	A. We have found that during a county-wide DCS Drill on Apr 26, 2015, that the 2m antenna system that was replaced by ISD last year has a very high SWR on all frequencies from 2m up through 70cm with a small dip to 3:1 around 300MHz. We can get into local repeaters, but Lomita can not hear us on simplex (they can hear another 2m radio running 5w into another antenna). The SWR on 2m is essentially infinite. This problem has also been reported previously.		
3.	Recommended Solution(s) A. Find and fix a break in the coaxial cable or replace the antenna.		
4.	Concurrences Date		
	Technical Team Contact	Norm Goodkin K-04, K6YXH@Goodkin.net	4-27-2015
	DCO	Tom Cagan, K-01, lacdcstom@gmail.com	4-27-2015
	Technical Ops Officer	Deane Bouvier, S-50, n5dq@arrl.net	5-11-2015
5.	CFMB Approval		