



Fig. 2: (a) Connection of 50 ohm feed cable with sm brass or copper clips, (b), (c) & (d) Methods of attaching aerial to mast.

Fig. 1: (a) General configuration showing voltage a current distribution, (b) Details of capacitance plate.

WAD