


DX-70T External Amplifier Relay Modification



Locate and cut or remove R534

****NOTE**** Any damage done while performing this modification will void any and all warranties.