

Location	Frequency	Comments (2/26/23)
<u>SFARES Repeaters</u>		
Tesuque Peak	146.820 MHz (-600, 162.2) 442.825 MHz (+5, 131.8)	Seems to receive but no transmit Working - Hub for the linked repeaters (UHF linking frequency for TESLINK 147.02 ARES repeater is working 144.39 APRS digi - last tested worked
St. Vincent's Hospital	147.200 MHz (+600, 162.2)	Working but not the greatest receive
Elk Mountain	147.300 MHz (+600, 162.2)	Working as stand-alone; not linked back to Tesuque Peak (Alan, N5BGC, has a link radio for it when the snow melts)
<u>Other Repeaters</u>		
San Antonio Mt.	146.760 MHz (-600, 67.0)	
Chama	147.08	Battery problems. Alan is working with owner, W5INB to make operational
Pajarito Mountain	145.19	No response