




TX CLOCK

The connections to U12B pins 8 & 9 were swapped. Cuts and jumpers added to correct. This shows correct configuration.

R86 & R87 Not Installed

NI = Component Not Installed

Title Exciter Modulator & Quadrature Divider		
Size D	Number	Rev 0
Date	Drawn by PAlexander	
Filename	Sheet 5	of 7